

SOILS

Map Unit Name (Series and Phase):		Soils from mixed origin		Drainage Class:	_____
Taxonomy (Subgroup):		_____		Field Observations	_____
				Confirm Mapped Type?	<input type="checkbox"/> Yes <input type="checkbox"/> No

Depth (inches)	Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc,

Hydric Soil Indicators:

<input type="checkbox"/> Histosol	<input type="checkbox"/> Concretions
<input type="checkbox"/> Histic Epipedon	<input type="checkbox"/> High Organic Content in Surface Layer in Sandy Soils
<input type="checkbox"/> Sulfidic Odor	<input type="checkbox"/> Organic Streaking in Sandy Soils
<input type="checkbox"/> Aquic Moisture Regime	<input type="checkbox"/> Listed on Local Hydric Soils List
<input type="checkbox"/> Reducing Conditions	<input type="checkbox"/> Listed on National Hydric Soils List
<input type="checkbox"/> Gleyed or Low-Chroma Colors	<input type="checkbox"/> Other (Explain in Remarks)

Remarks: Paved road

WETLAND DETERMINATION

Hydrophytic Vegetation Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No (Check)	(Check)
Wetland Hydrology Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Hydric Soils Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Is this Sampling Point Within a Wetland? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Remarks	

DATA FORM
ROUTINE WETLAND DETERMINATION
(1987 COE Wetlands Delineation Manual)

Project/Site: <u>Tranvia de Carolina</u>	Date: <u>Jan 2007</u>
Applicant/Owner: <u>AFI, Municipio Carolina</u>	County: <u>Carolina</u>
Investigator: <u>RiveraLugo, PJ</u>	State: <u>Puerto Rico</u>
Do Normal Circumstances exist on the site? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Community ID: _____
Is the site significantly disturbed (Atypical Situation)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Transect ID: <u>42</u>
Is the area a potential Problem Area? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Plot ID: <u>b</u>
(If needed, explain on reverse.)	

VEGETATION

Dominant Plant Species	Stratum	Indicator	Dominant Plant Species	Stratum	Indicator
1. <u>Bucidas buceras</u>	<u>T</u>	<u>FAC</u>	9. _____	_____	_____
2. <u>Tabebuia heterophylla</u>	<u>T</u>	<u>FAC</u>	10. _____	_____	_____
3. _____	_____	_____	11. _____	_____	_____
4. _____	_____	_____	12. _____	_____	_____
5. _____	_____	_____	13. _____	_____	_____
6. _____	_____	_____	14. _____	_____	_____
7. _____	_____	_____	15. _____	_____	_____
8. _____	_____	_____	16. _____	_____	_____
Percent of Dominant Species that are OBL, FACW or FAC (excluding FAC-).					
Remarks:					

HYDROLOGY

<input type="checkbox"/> Recorded Data (Describe in Remarks): <input type="checkbox"/> Stream, Lake, or Tide Gauge <input type="checkbox"/> Aerial Photographs <input type="checkbox"/> Other <input type="checkbox"/> No Recorded Data Available	Wetland Hydrology Indicators: Primary Indicators: <input type="checkbox"/> Inundated <input type="checkbox"/> Saturated in Upper 12 Inches <input type="checkbox"/> Water Marks <input type="checkbox"/> Drift Lines <input type="checkbox"/> Sediment Deposits <input type="checkbox"/> Drainage Patterns in Wetlands Secondary Indicators (2 or more required): <input type="checkbox"/> Oxidized Root Channels in Upper 12 Inches <input type="checkbox"/> Water-Stained Leaves <input type="checkbox"/> Local Soil Survey Data <input type="checkbox"/> FAC-Neutral Test <input type="checkbox"/> Other (Explain in Remarks)
Field Observations: Depth of Surface Water: _____ (in.) Depth to Free Water in Pit: _____ (in.) Depth to Saturated Soil: _____ (in.)	
Remarks:	

SOILS

Map Unit Name (Series and Phase):		Soils from mixed origin		Drainage Class:	
Taxonomy (Subgroup):				Field Observations	
				Confirm Mapped Type?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Profile Descriptions:					
Depth (inches)	Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc,
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
Hydric Soil Indicators:					
<input type="checkbox"/> Histosol	<input type="checkbox"/> Histic Epipedon	<input type="checkbox"/> Sulfidic Odor	<input type="checkbox"/> Aquic Moisture Regime	<input type="checkbox"/> Reducing Conditions	<input type="checkbox"/> Gleyed or Low-Chroma Colors
<input type="checkbox"/> Concretions	<input type="checkbox"/> High Organic Content in Surface Layer in Sandy Soils	<input type="checkbox"/> Organic Streaking in Sandy Soils	<input type="checkbox"/> Listed on Local Hydric Soils List	<input type="checkbox"/> Listed on National Hydric Soils List	<input type="checkbox"/> Other (Explain in Remarks)
Remarks: Paved road					

WETLAND DETERMINATION

Hydrophytic Vegetation Present?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	(Check)		
Wetland Hydrology Present?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No			
Hydric Soils Present?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No			
				Is this Sampling Point Within a Wetland?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Remarks					

DATA FORM
ROUTINE WETLAND DETERMINATION
(1987 COE Wetlands Delineation Manual)

Project/Site: <u>Tranvia de Carolina</u>	Date: <u>Jan 2007</u>
Applicant/Owner: <u>AFI, Municipio Carolina</u>	County: <u>Carolina</u>
Investigator: <u>RiveraLugo, PJ</u>	State: <u>Puerto Rico</u>
Do Normal Circumstances exist on the site? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Community ID: _____
Is the site significantly disturbed (Atypical Situation)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Transect ID: <u>42</u>
Is the area a potential Problem Area? (If needed, explain on reverse.) <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Plot ID: <u>a</u>

VEGETATION

Dominant Plant Species	Stratum	Indicator	Dominant Plant Species	Stratum	Indicator
1. <u>Bucidas buceras</u>	<u>T</u>	<u>FAC</u>	9. _____	_____	_____
2. <u>Tabebuia heterophylla</u>	<u>T</u>	<u>FAC</u>	10. _____	_____	_____
3. _____	_____	_____	11. _____	_____	_____
4. _____	_____	_____	12. _____	_____	_____
5. _____	_____	_____	13. _____	_____	_____
6. _____	_____	_____	14. _____	_____	_____
7. _____	_____	_____	15. _____	_____	_____
8. _____	_____	_____	16. _____	_____	_____

Percent of Dominant Species that are OBL, FACW or FAC (excluding FAC-). _____

Remarks: _____

HYDROLOGY

<input type="checkbox"/> Recorded Data (Describe in Remarks): <input type="checkbox"/> Stream, Lake, or Tide Gauge <input type="checkbox"/> Aerial Photographs <input type="checkbox"/> Other <input type="checkbox"/> No Recorded Data Available	Wetland Hydrology Indicators: Primary Indicators: <input type="checkbox"/> Inundated <input type="checkbox"/> Saturated in Upper 12 Inches <input type="checkbox"/> Water Marks <input type="checkbox"/> Drift Lines <input type="checkbox"/> Sediment Deposits <input type="checkbox"/> Drainage Patterns in Wetlands Secondary Indicators (2 or more required): <input type="checkbox"/> Oxidized Root Channels in Upper 12 Inches <input type="checkbox"/> Water-Stained Leaves <input type="checkbox"/> Local Soil Survey Data <input type="checkbox"/> FAC-Neutral Test <input type="checkbox"/> Other (Explain in Remarks)
Field Observations: Depth of Surface Water: _____ (in.) Depth to Free Water in Pit: _____ (in.) Depth to Saturated Soil: _____ (in.)	
Remarks: _____	

SOILS

Map Unit Name (Series and Phase):		Soils form mixed origin, paved		Drainage Class:	_____
Taxonomy (Subgroup):		_____		Field Observations	_____
				Confirm Mapped Type?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Profile Descriptions:					
Depth (inches)	Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc,
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
Hydric Soil Indicators:					
<input type="checkbox"/> Histosol	<input type="checkbox"/> Histic Epipedon	<input type="checkbox"/> Sulfidic Odor	<input type="checkbox"/> Aquic Moisture Regime	<input type="checkbox"/> Reducing Conditions	<input type="checkbox"/> Gleyed or Low-Chroma Colors
<input type="checkbox"/> Concretions	<input type="checkbox"/> High Organic Content in Surface Layer in Sandy Soils	<input type="checkbox"/> Organic Streaking in Sandy Soils	<input type="checkbox"/> Listed on Local Hydric Soils List	<input type="checkbox"/> Listed on National Hydric Soils List	<input type="checkbox"/> Other (Explain in Remarks)
Remarks:					

WETLAND DETERMINATION

Hydrophytic Vegetation Present?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	(Check)		
Wetland Hydrology Present?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No			
Hydric Soils Present?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No			
				Is this Sampling Point Within a Wetland?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Remarks					

DATA FORM
ROUTINE WETLAND DETERMINATION
(1987 COE Wetlands Delineation Manual)

Project/Site: <u>Tranvia de Carolina</u>	Date: <u>Jan 2007</u>
Applicant/Owner: <u>AFI, Municipio Carolina</u>	County: <u>Carolina</u>
Investigator: <u>RiveraLugo,PJ</u>	State: <u>Puerto Rico</u>
Do Normal Circumstances exist on the site? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Community ID: _____
Is the site significantly disturbed (Atypical Situation)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Transect ID: <u>41</u>
Is the area a potential Problem Area? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No (If needed, explain on reverse.)	Plot ID: <u>c</u>

VEGETATION

Dominant Plant Species	Stratum	Indicator	Dominant Plant Species	Stratum	Indicator
1. <u>Ixora coccinea</u>	<u>S</u>	<u>NI</u>	9. _____	_____	_____
2. <u>Syagrus romazifolium</u>	<u>T</u>	<u>NI</u>	10. _____	_____	_____
3. <u>Cynodon dactylon</u>	<u>H</u>	<u>FAC</u>	11. _____	_____	_____
4. <u>Roystonea borinquena</u>	<u>T</u>	<u>FAC</u>	12. _____	_____	_____
5. <u>Pterocarpus indicus</u>	<u>T</u>	<u>NI</u>	13. _____	_____	_____
6. <u>Tabebuia aurea</u>	<u>T</u>	<u>NI</u>	14. _____	_____	_____
7. _____	_____	_____	15. _____	_____	_____
8. _____	_____	_____	16. _____	_____	_____

Percent of Dominant Species that are OBL, FACW or FAC (excluding FAC-): _____

Remarks: _____

HYDROLOGY

<input type="checkbox"/> Recorded Data (Describe in Remarks): <input type="checkbox"/> Stream, Lake, or Tide Gauge <input type="checkbox"/> Aerial Photographs <input type="checkbox"/> Other <input type="checkbox"/> No Recorded Data Available	Wetland Hydrology Indicators: Primary Indicators: <input type="checkbox"/> Inundated <input type="checkbox"/> Saturated in Upper 12 Inches <input type="checkbox"/> Water Marks <input type="checkbox"/> Drift Lines <input type="checkbox"/> Sediment Deposits <input type="checkbox"/> Drainage Patterns in Wetlands Secondary Indicators (2 or more required): <input type="checkbox"/> Oxidized Root Channels in Upper 12 Inches <input type="checkbox"/> Water-Stained Leaves <input type="checkbox"/> Local Soil Survey Data <input type="checkbox"/> FAC-Neutral Test <input type="checkbox"/> Other (Explain in Remarks)
Field Observations: Depth of Surface Water: _____ (in.) Depth to Free Water in Pit: _____ (in.) Depth to Saturated Soil: _____ (in.)	
Remarks: _____	

SOILS

Map Unit Name (Series and Phase):		Soils form mixed origin, paved		Drainage Class:	_____
Taxonomy (Subgroup):		_____		Field Observations	_____
				Confirm Mapped Type?	<input type="checkbox"/> Yes <input type="checkbox"/> No

Profile Descriptions:	Depth (inches)	Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc,

Hydric Soil Indicators:

<input type="checkbox"/> Histosol	<input type="checkbox"/> Concretions
<input type="checkbox"/> Histic Epipedon	<input type="checkbox"/> High Organic Content in Surface Layer in Sandy Soils
<input type="checkbox"/> Sulfidic Odor	<input type="checkbox"/> Organic Streaking in Sandy Soils
<input type="checkbox"/> Aquic Moisture Regime	<input type="checkbox"/> Listed on Local Hydric Soils List
<input type="checkbox"/> Reducing Conditions	<input type="checkbox"/> Listed on National Hydric Soils List
<input type="checkbox"/> Gleyed or Low-Chroma Colors	<input type="checkbox"/> Other (Explain in Remarks)

Remarks:

WETLAND DETERMINATION

<p>Hydrophytic Vegetation Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No (Check)</p> <p>Wetland Hydrology Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p> <p>Hydric Soils Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p>	<p>(Check)</p> <p>Is this Sampling Point Within a Wetland? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p>
<p>Remarks</p>	

DATA FORM
ROUTINE WETLAND DETERMINATION
(1987 COE Wetlands Delineation Manual)

Project/Site: <u>Tranvia de Carolina</u>	Date: <u>Jan 2007</u>
Applicant/Owner: <u>AFI, Municipio Carolina</u>	County: <u>Carolina</u>
Investigator: <u>RiveraLugo, PJ</u>	State: <u>Puerto Rico</u>
Do Normal Circumstances exist on the site? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Community ID: _____
Is the site significantly disturbed (Atypical Situation)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Transect ID: <u>41</u>
Is the area a potential Problem Area? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Plot ID: <u>b</u>
(If needed, explain on reverse.)	

VEGETATION

Dominant Plant Species	Stratum	Indicator	Dominant Plant Species	Stratum	Indicator
1. <u>Ixora coccinea</u>	<u>S</u>	<u>NI</u>	9. _____	_____	_____
2. <u>Syagrus romazifolium</u>	<u>T</u>	<u>NI</u>	10. _____	_____	_____
3. <u>Cynodon dactylon</u>	<u>H</u>	<u>FAC</u>	11. _____	_____	_____
4. <u>Roystonea borinquena</u>	<u>T</u>	<u>FAC</u>	12. _____	_____	_____
5. <u>Pterocarpus indicus</u>	<u>T</u>	<u>NI</u>	13. _____	_____	_____
6. <u>Tabebuia aurea</u>	<u>T</u>	<u>NI</u>	14. _____	_____	_____
7. _____	_____	_____	15. _____	_____	_____
8. _____	_____	_____	16. _____	_____	_____

Percent of Dominant Species that are OBL, FACW or FAC (excluding FAC-): _____

Remarks: _____

HYDROLOGY

<input type="checkbox"/> Recorded Data (Describe in Remarks): <input type="checkbox"/> Stream, Lake, or Tide Gauge <input type="checkbox"/> Aerial Photographs <input type="checkbox"/> Other <input type="checkbox"/> No Recorded Data Available	Wetland Hydrology Indicators: Primary Indicators: <input type="checkbox"/> Inundated <input type="checkbox"/> Saturated in Upper 12 Inches <input type="checkbox"/> Water Marks <input type="checkbox"/> Drift Lines <input type="checkbox"/> Sediment Deposits <input type="checkbox"/> Drainage Patterns in Wetlands Secondary Indicators (2 or more required): <input type="checkbox"/> Oxidized Root Channels in Upper 12 Inches <input type="checkbox"/> Water-Stained Leaves <input type="checkbox"/> Local Soil Survey Data <input type="checkbox"/> FAC-Neutral Test <input type="checkbox"/> Other (Explain in Remarks)
Field Observations: Depth of Surface Water: _____ (in.) Depth to Free Water in Pit: _____ (in.) Depth to Saturated Soil: _____ (in.)	
Remarks: _____	

SOILS

Map Unit Name (Series and Phase):		Soils form mixed origin, paved		Drainage Class:	_____
Taxonomy (Subgroup):		_____		Field Observations	_____
				Confirm Mapped Type?	<input type="checkbox"/> Yes <input type="checkbox"/> No

Profile Descriptions:	Depth (inches)	Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc,

Hydric Soil Indicators:

<input type="checkbox"/> Histosol	<input type="checkbox"/> Concretions
<input type="checkbox"/> Histic Epipedon	<input type="checkbox"/> High Organic Content in Surface Layer in Sandy Soils
<input type="checkbox"/> Sulfidic Odor	<input type="checkbox"/> Organic Streaking in Sandy Soils
<input type="checkbox"/> Aquic Moisture Regime	<input type="checkbox"/> Listed on Local Hydric Soils List
<input type="checkbox"/> Reducing Conditions	<input type="checkbox"/> Listed on National Hydric Soils List
<input type="checkbox"/> Gleyed or Low-Chroma Colors	<input type="checkbox"/> Other (Explain in Remarks)

Remarks:

WETLAND DETERMINATION

<p>Hydrophytic Vegetation Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No (Check)</p> <p>Wetland Hydrology Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p> <p>Hydric Soils Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p>	<p style="text-align: right;">(Check)</p> <p>Is this Sampling Point Within a Wetland? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p>
<p>Remarks</p>	

DATA FORM
ROUTINE WETLAND DETERMINATION
(1987 COE Wetlands Delineation Manual)

Project/Site: <u>Tranvia de Carolina</u>	Date: <u>Jan 2007</u>
Applicant/Owner: <u>AFI, Municipio Carolina</u>	County: <u>Carolina</u>
Investigator: <u>RiveraLugo,PJ</u>	State: <u>Puerto Rico</u>
Do Normal Circumstances exist on the site? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Community ID: _____
Is the site significantly disturbed (Atypical Situation)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Transect ID: <u>41</u>
Is the area a potential Problem Area? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Plot ID: <u>a</u>
(If needed, explain on reverse.)	

VEGETATION

Dominant Plant Species	Stratum	Indicator	Dominant Plant Species	Stratum	Indicator
1. <u>Ixora coccinea</u>	<u>S</u>	<u>NI</u>	9. _____	_____	_____
2. <u>Syagrus romazifolium</u>	<u>T</u>	<u>NI</u>	10. _____	_____	_____
3. <u>Cynodon dactylon</u>	<u>H</u>	<u>FAC</u>	11. _____	_____	_____
4. <u>Roystonea borinquena</u>	<u>T</u>	<u>FAC</u>	12. _____	_____	_____
5. <u>Pterocarpus indicus</u>	<u>T</u>	<u>NI</u>	13. _____	_____	_____
6. <u>Tabebuia aurea</u>	<u>T</u>	<u>NI</u>	14. _____	_____	_____
7. _____	_____	_____	15. _____	_____	_____
8. _____	_____	_____	16. _____	_____	_____

Percent of Dominant Species that are OBL, FACW or FAC (excluding FAC-): _____

Remarks: _____

HYDROLOGY

<input type="checkbox"/> Recorded Data (Describe in Remarks): <input type="checkbox"/> Stream, Lake, or Tide Gauge <input type="checkbox"/> Aerial Photographs <input type="checkbox"/> Other <input type="checkbox"/> No Recorded Data Available	Wetland Hydrology Indicators: Primary Indicators: <input type="checkbox"/> Inundated <input type="checkbox"/> Saturated in Upper 12 Inches <input type="checkbox"/> Water Marks <input type="checkbox"/> Drift Lines <input type="checkbox"/> Sediment Deposits <input type="checkbox"/> Drainage Patterns in Wetlands Secondary Indicators (2 or more required): <input type="checkbox"/> Oxidized Root Channels in Upper 12 Inches <input type="checkbox"/> Water-Stained Leaves <input type="checkbox"/> Local Soil Survey Data <input type="checkbox"/> FAC-Neutral Test <input type="checkbox"/> Other (Explain in Remarks)
Field Observations: Depth of Surface Water: _____ (in.) Depth to Free Water in Pit: _____ (in.) Depth to Saturated Soil: _____ (in.)	
Remarks: _____	

SOILS

Map Unit Name (Series and Phase):		Soils from mixed origin, paved		Drainage Class:	_____
Taxonomy (Subgroup):		_____		Field Observations	_____
				Confirm Mapped Type?	<input type="checkbox"/> Yes <input type="checkbox"/> No

Profile Descriptions:	Depth (inches)	Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc,

Hydric Soil Indicators:

<input type="checkbox"/> Histosol	<input type="checkbox"/> Concretions
<input type="checkbox"/> Histic Epipedon	<input type="checkbox"/> High Organic Content in Surface Layer in Sandy Soils
<input type="checkbox"/> Sulfidic Odor	<input type="checkbox"/> Organic Streaking in Sandy Soils
<input type="checkbox"/> Aquic Moisture Regime	<input type="checkbox"/> Listed on Local Hydric Soils List
<input type="checkbox"/> Reducing Conditions	<input type="checkbox"/> Listed on National Hydric Soils List
<input type="checkbox"/> Gleyed or Low-Chroma Colors	<input type="checkbox"/> Other (Explain in Remarks)

Remarks:

WETLAND DETERMINATION

Hydrophytic Vegetation Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No (Check) Wetland Hydrology Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Hydric Soils Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	(Check) Is this Sampling Point Within a Wetland? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Remarks	

DATA FORM
ROUTINE WETLAND DETERMINATION
(1987 COE Wetlands Delineation Manual)

Project/Site: <u>Tranvia de Carolina</u>	Date: <u>Jan 2007</u>
Applicant/Owner: <u>AFI, Municipio Carolina</u>	County: <u>Carolina</u>
Investigator: <u>RiveraLugo,PJ</u>	State: <u>Puerto Rico</u>
Do Normal Circumstances exist on the site? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Community ID: _____
Is the site significantly disturbed (Atypical Situation)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Transect ID: <u>40</u>
Is the area a potential Problem Area? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Plot ID: <u>c</u>
(If needed, explain on reverse.)	

VEGETATION

Dominant Plant Species	Stratum	Indicator	Dominant Plant Species	Stratum	Indicator
1. <u>Tabebuia aurea</u>	<u>T</u>	<u>NI</u>	9. _____	_____	_____
2. <u>Pterocarpus indicus</u>	<u>T</u>	<u>NI</u>	10. _____	_____	_____
3. <u>Bounganvillea sp</u>	<u>S</u>	<u>NI</u>	11. _____	_____	_____
4. <u>Cynodon dactylon</u>	<u>H</u>	<u>FAC</u>	12. _____	_____	_____
5. _____	_____	_____	13. _____	_____	_____
6. _____	_____	_____	14. _____	_____	_____
7. _____	_____	_____	15. _____	_____	_____
8. _____	_____	_____	16. _____	_____	_____

Percent of Dominant Species that are OBL, FACW or FAC (excluding FAC-): _____

Remarks: _____

HYDROLOGY

<input type="checkbox"/> Recorded Data (Describe in Remarks): <input type="checkbox"/> Stream, Lake, or Tide Gauge <input type="checkbox"/> Aerial Photographs <input type="checkbox"/> Other <input type="checkbox"/> No Recorded Data Available	Wetland Hydrology Indicators: Primary Indicators: <input type="checkbox"/> Inundated <input type="checkbox"/> Saturated in Upper 12 Inches <input type="checkbox"/> Water Marks <input type="checkbox"/> Drift Lines <input type="checkbox"/> Sediment Deposits <input type="checkbox"/> Drainage Patterns in Wetlands Secondary Indicators (2 or more required): <input type="checkbox"/> Oxidized Root Channels in Upper 12 Inches <input type="checkbox"/> Water-Stained Leaves <input type="checkbox"/> Local Soil Survey Data <input type="checkbox"/> FAC-Neutral Test <input type="checkbox"/> Other (Explain in Remarks)
Field Observations: Depth of Surface Water: _____ (in.) Depth to Free Water in Pit: _____ (in.) Depth to Saturated Soil: _____ (in.)	
Remarks: _____	

SOILS

Map Unit Name (Series and Phase):		Soils from mixed origin, paved		Drainage Class:	_____
Taxonomy (Subgroup):		_____		Field Observations	_____
				Confirm Mapped Type?	<input type="checkbox"/> Yes <input type="checkbox"/> No

Profile Descriptions:	Depth (inches)	Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc,

Hydric Soil Indicators:

<input type="checkbox"/> Histosol	<input type="checkbox"/> Concretions
<input type="checkbox"/> Histic Epipedon	<input type="checkbox"/> High Organic Content in Surface Layer in Sandy Soils
<input type="checkbox"/> Sulfidic Odor	<input type="checkbox"/> Organic Streaking in Sandy Soils
<input type="checkbox"/> Aquic Moisture Regime	<input type="checkbox"/> Listed on Local Hydric Soils List
<input type="checkbox"/> Reducing Conditions	<input type="checkbox"/> Listed on National Hydric Soils List
<input type="checkbox"/> Gleyed or Low-Chroma Colors	<input type="checkbox"/> Other (Explain in Remarks)

Remarks:

WETLAND DETERMINATION

<p>Hydrophytic Vegetation Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No (Check)</p> <p>Wetland Hydrology Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p> <p>Hydric Soils Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p>	<p style="text-align: right;">(Check)</p> <p>Is this Sampling Point Within a Wetland? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p>
<p>Remarks</p>	

DATA FORM
ROUTINE WETLAND DETERMINATION
(1987 COE Wetlands Delineation Manual)

Project/Site: <u>Tranvia de Carolina</u>	Date: <u>Jan 2007</u>
Applicant/Owner: <u>AFI, Municipio Carolina</u>	County: <u>Carolina</u>
Investigator: <u>RiveraLugo,PJ</u>	State: <u>Puerto Rico</u>
Do Normal Circumstances exist on the site? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Community ID: _____
Is the site significantly disturbed (Atypical Situation)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Transect ID: <u>40</u>
Is the area a potential Problem Area? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Plot ID: <u>b</u>
(If needed, explain on reverse.)	

VEGETATION

Dominant Plant Species	Stratum	Indicator	Dominant Plant Species	Stratum	Indicator
1. <u>Tabebuia aurea</u>	<u>T</u>	<u>NI</u>	9. _____	_____	_____
2. <u>Pterocarpus indicus</u>	<u>T</u>	<u>NI</u>	10. _____	_____	_____
3. <u>Bounganvillea sp</u>	<u>S</u>	<u>NI</u>	11. _____	_____	_____
4. <u>Cynodon dactylon</u>	<u>H</u>	<u>FAC</u>	12. _____	_____	_____
5. _____	_____	_____	13. _____	_____	_____
6. _____	_____	_____	14. _____	_____	_____
7. _____	_____	_____	15. _____	_____	_____
8. _____	_____	_____	16. _____	_____	_____

Percent of Dominant Species that are OBL, FACW or FAC (excluding FAC-): _____

Remarks: _____

HYDROLOGY

<input type="checkbox"/> Recorded Data (Describe in Remarks): <input type="checkbox"/> Stream, Lake, or Tide Gauge <input type="checkbox"/> Aerial Photographs <input type="checkbox"/> Other <input type="checkbox"/> No Recorded Data Available	Wetland Hydrology Indicators: Primary Indicators: <input type="checkbox"/> Inundated <input type="checkbox"/> Saturated in Upper 12 Inches <input type="checkbox"/> Water Marks <input type="checkbox"/> Drift Lines <input type="checkbox"/> Sediment Deposits <input type="checkbox"/> Drainage Patterns in Wetlands Secondary Indicators (2 or more required): <input type="checkbox"/> Oxidized Root Channels in Upper 12 Inches <input type="checkbox"/> Water-Stained Leaves <input type="checkbox"/> Local Soil Survey Data <input type="checkbox"/> FAC-Neutral Test <input type="checkbox"/> Other (Explain in Remarks)
Field Observations: Depth of Surface Water: _____ (in.) Depth to Free Water in Pit: _____ (in.) Depth to Saturated Soil: _____ (in.)	
Remarks: _____	

SOILS

Map Unit Name (Series and Phase):		Soils from mixed origin, paved		Drainage Class:	_____
Taxonomy (Subgroup):		_____		Field Observations	_____
				Confirm Mapped Type?	<input type="checkbox"/> Yes <input type="checkbox"/> No

Profile Descriptions: Depth (inches)	Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc,

Hydric Soil Indicators:

<input type="checkbox"/> Histosol	<input type="checkbox"/> Concretions
<input type="checkbox"/> Histic Epipedon	<input type="checkbox"/> High Organic Content in Surface Layer in Sandy Soils
<input type="checkbox"/> Sulfidic Odor	<input type="checkbox"/> Organic Streaking in Sandy Soils
<input type="checkbox"/> Aquic Moisture Regime	<input type="checkbox"/> Listed on Local Hydric Soils List
<input type="checkbox"/> Reducing Conditions	<input type="checkbox"/> Listed on National Hydric Soils List
<input type="checkbox"/> Gleyed or Low-Chroma Colors	<input type="checkbox"/> Other (Explain in Remarks)

Remarks:

WETLAND DETERMINATION

Hydrophytic Vegetation Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No (Check) Wetland Hydrology Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Hydric Soils Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	_____ (Check) Is this Sampling Point Within a Wetland? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Remarks	

DATA FORM
ROUTINE WETLAND DETERMINATION
(1987 COE Wetlands Delineation Manual)

Project/Site: <u>Tranvia de Carolina</u>	Date: <u>Jan 2007</u>
Applicant/Owner: <u>AFI, Municipio Carolina</u>	County: <u>Carolina</u>
Investigator: <u>RiveraLugo,PJ</u>	State: <u>Puerto Rico</u>
Do Normal Circumstances exist on the site? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Community ID: _____
Is the site significantly disturbed (Atypical Situation)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Transect ID: <u>40</u>
Is the area a potential Problem Area? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Plot ID: <u>a</u>
(If needed, explain on reverse.)	

VEGETATION

Dominant Plant Species	Stratum	Indicator	Dominant Plant Species	Stratum	Indicator
1. <u>Tabebuia aurea</u>	<u>T</u>	<u>NI</u>	9. _____	_____	_____
2. <u>Pterocarpus indicus</u>	<u>T</u>	<u>NI</u>	10. _____	_____	_____
3. <u>Bounganvillea sp</u>	<u>S</u>	<u>NI</u>	11. _____	_____	_____
4. <u>Cynodon dactylon</u>	<u>H</u>	<u>FAC</u>	12. _____	_____	_____
5. _____	_____	_____	13. _____	_____	_____
6. _____	_____	_____	14. _____	_____	_____
7. _____	_____	_____	15. _____	_____	_____
8. _____	_____	_____	16. _____	_____	_____

Percent of Dominant Species that are OBL, FACW or FAC (excluding FAC-): _____

Remarks: _____

HYDROLOGY

<input type="checkbox"/> Recorded Data (Describe in Remarks): <input type="checkbox"/> Stream, Lake, or Tide Gauge <input type="checkbox"/> Aerial Photographs <input type="checkbox"/> Other <input type="checkbox"/> No Recorded Data Available	Wetland Hydrology Indicators: Primary Indicators: <input type="checkbox"/> Inundated <input type="checkbox"/> Saturated in Upper 12 Inches <input type="checkbox"/> Water Marks <input type="checkbox"/> Drift Lines <input type="checkbox"/> Sediment Deposits <input type="checkbox"/> Drainage Patterns in Wetlands Secondary Indicators (2 or more required): <input type="checkbox"/> Oxidized Root Channels in Upper 12 Inches <input type="checkbox"/> Water-Stained Leaves <input type="checkbox"/> Local Soil Survey Data <input type="checkbox"/> FAC-Neutral Test <input type="checkbox"/> Other (Explain in Remarks)
Field Observations: Depth of Surface Water: _____ (in.) Depth to Free Water in Pit: _____ (in.) Depth to Saturated Soil: _____ (in.)	
Remarks: _____	

SOILS

Map Unit Name (Series and Phase):		<u>Soils from mixed origin, paved</u>		Drainage Class:	_____
Taxonomy (Subgroup):		_____		Field Observations	_____
				Confirm Mapped Type?	<input type="checkbox"/> Yes <input type="checkbox"/> No

Profile Descriptions:					
Depth (inches)	Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc,
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____

Hydric Soil Indicators:

<input type="checkbox"/> Histosol	<input type="checkbox"/> Concretions
<input type="checkbox"/> Histic Epipedon	<input type="checkbox"/> High Organic Content in Surface Layer in Sandy Soils
<input type="checkbox"/> Sulfidic Odor	<input type="checkbox"/> Organic Streaking in Sandy Soils
<input type="checkbox"/> Aquic Moisture Regime	<input type="checkbox"/> Listed on Local Hydric Soils List
<input type="checkbox"/> Reducing Conditions	<input type="checkbox"/> Listed on National Hydric Soils List
<input type="checkbox"/> Gleyed or Low-Chroma Colors	<input type="checkbox"/> Other (Explain in Remarks)

Remarks:

WETLAND DETERMINATION

Hydrophytic Vegetation Present?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	(Check)
Wetland Hydrology Present?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	(Check)
Hydric Soils Present?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Is this Sampling Point Within a Wetland?
		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Remarks		

DATA FORM
ROUTINE WETLAND DETERMINATION
(1987 COE Wetlands Delineation Manual)

Project/Site: <u>Tranvia de Carolina</u>	Date: <u>Jan 2007</u>
Applicant/Owner: <u>AFI, Municipio Carolina</u>	County: <u>Carolina</u>
Investigator: <u>RiveraLugo, PJ</u>	State: <u>Puerto Rico</u>
Do Normal Circumstances exist on the site? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Community ID: _____
Is the site significantly disturbed (Atypical Situation)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Transect ID: <u>39</u>
Is the area a potential Problem Area? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No (If needed, explain on reverse.)	Plot ID: <u>c</u>

VEGETATION

Dominant Plant Species	Stratum	Indicator	Dominant Plant Species	Stratum	Indicator
1. <u>Tabebuia rosea</u>	<u>T</u>	<u>NI</u>	9. _____	_____	_____
2. <u>Tabebuia heterophylla</u>	<u>T</u>	<u>FAC</u>	10. _____	_____	_____
3. <u>Albizia procera</u>	<u>T</u>	<u>NI</u>	11. _____	_____	_____
4. <u>Roystonea borinquena</u>	<u>T</u>	<u>FAC</u>	12. _____	_____	_____
5. <u>Sphagneticola trilobataH</u>	<u>NI</u>	<u>NI</u>	13. _____	_____	_____
6. _____	_____	_____	14. _____	_____	_____
7. _____	_____	_____	15. _____	_____	_____
8. _____	_____	_____	16. _____	_____	_____

Percent of Dominant Species that are OBL, FACW or FAC (excluding FAC-): _____

Remarks: _____

HYDROLOGY

<input type="checkbox"/> Recorded Data (Describe in Remarks): <input type="checkbox"/> Stream, Lake, or Tide Gauge <input type="checkbox"/> Aerial Photographs <input type="checkbox"/> Other <input type="checkbox"/> No Recorded Data Available	Wetland Hydrology Indicators: Primary Indicators: <input type="checkbox"/> Inundated <input type="checkbox"/> Saturated in Upper 12 Inches <input type="checkbox"/> Water Marks <input type="checkbox"/> Drift Lines <input type="checkbox"/> Sediment Deposits <input type="checkbox"/> Drainage Patterns in Wetlands Secondary Indicators (2 or more required): <input type="checkbox"/> Oxidized Root Channels in Upper 12 Inches <input type="checkbox"/> Water-Stained Leaves <input type="checkbox"/> Local Soil Survey Data <input type="checkbox"/> FAC-Neutral Test <input type="checkbox"/> Other (Explain in Remarks)
Field Observations: Depth of Surface Water: _____ (in.) Depth to Free Water in Pit: _____ (in.) Depth to Saturated Soil: _____ (in.)	
Remarks: _____	

SOILS

Map Unit Name (Series and Phase):		Soils from mixed origin, paved		Drainage Class:	_____
Taxonomy (Subgroup):		_____		Field Observations	_____
				Confirm Mapped Type?	<input type="checkbox"/> Yes <input type="checkbox"/> No

Profile Descriptions:	Depth (inches)	Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc,

Hydric Soil Indicators:

<input type="checkbox"/> Histosol	<input type="checkbox"/> Concretions
<input type="checkbox"/> Histic Epipedon	<input type="checkbox"/> High Organic Content in Surface Layer in Sandy Soils
<input type="checkbox"/> Sulfidic Odor	<input type="checkbox"/> Organic Streaking in Sandy Soils
<input type="checkbox"/> Aquic Moisture Regime	<input type="checkbox"/> Listed on Local Hydric Soils List
<input type="checkbox"/> Reducing Conditions	<input type="checkbox"/> Listed on National Hydric Soils List
<input type="checkbox"/> Gleyed or Low-Chroma Colors	<input type="checkbox"/> Other (Explain in Remarks)

Remarks:

WETLAND DETERMINATION

Hydrophytic Vegetation Present?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	(Check)		
Wetland Hydrology Present?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No			
Hydric Soils Present?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No		Is this Sampling Point Within a Wetland?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No

Remarks

DATA FORM
ROUTINE WETLAND DETERMINATION
(1987 COE Wetlands Delineation Manual)

Project/Site: <u>Tranvia de Carolina</u>	Date: <u>Jan 2007</u>
Applicant/Owner: <u>AFI, Municipio Carolina</u>	County: <u>Carolina</u>
Investigator: <u>RiveraLugo, PJ</u>	State: <u>Puerto Rico</u>
Do Normal Circumstances exist on the site? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Community ID: _____
Is the site significantly disturbed (Atypical Situation)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Transect ID: <u>39</u>
Is the area a potential Problem Area? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Plot ID: <u>b</u>
(If needed, explain on reverse.)	

VEGETATION

Dominant Plant Species	Stratum	Indicator	Dominant Plant Species	Stratum	Indicator
1. <u>Tabebuia rosea</u>	<u>T</u>	<u>NI</u>	9. _____	_____	_____
2. <u>Tabebuia heterophylla</u>	<u>T</u>	<u>FAC</u>	10. _____	_____	_____
3. <u>Albizia procera</u>	<u>T</u>	<u>NI</u>	11. _____	_____	_____
4. <u>Roystonea borinquena</u>	<u>T</u>	<u>FAC</u>	12. _____	_____	_____
5. <u>Sphagneticola trilobataH</u>	<u>NI</u>	_____	13. _____	_____	_____
6. _____	_____	_____	14. _____	_____	_____
7. _____	_____	_____	15. _____	_____	_____
8. _____	_____	_____	16. _____	_____	_____

Percent of Dominant Species that are OBL, FACW or FAC (excluding FAC-): _____

Remarks: _____

HYDROLOGY

<input type="checkbox"/> Recorded Data (Describe in Remarks): <input type="checkbox"/> Stream, Lake, or Tide Gauge <input type="checkbox"/> Aerial Photographs <input type="checkbox"/> Other <input type="checkbox"/> No Recorded Data Available	Wetland Hydrology Indicators: Primary Indicators: <input type="checkbox"/> Inundated <input type="checkbox"/> Saturated in Upper 12 Inches <input type="checkbox"/> Water Marks <input type="checkbox"/> Drift Lines <input type="checkbox"/> Sediment Deposits <input type="checkbox"/> Drainage Patterns in Wetlands Secondary Indicators (2 or more required): <input type="checkbox"/> Oxidized Root Channels in Upper 12 Inches <input type="checkbox"/> Water-Stained Leaves <input type="checkbox"/> Local Soil Survey Data <input type="checkbox"/> FAC-Neutral Test <input type="checkbox"/> Other (Explain in Remarks)
Field Observations: Depth of Surface Water: _____ (in.) Depth to Free Water in Pit: _____ (in.) Depth to Saturated Soil: _____ (in.)	
Remarks: _____	

SOILS

Map Unit Name (Series and Phase):		<u>Soils from mixed origin, paved</u>		Drainage Class:	_____
Taxonomy (Subgroup):		_____		Field Observations	_____
				Confirm Mapped Type?	<input type="checkbox"/> Yes <input type="checkbox"/> No

Profile Descriptions:	Depth (inches)	Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc,

Hydric Soil Indicators:

<input type="checkbox"/> Histosol	<input type="checkbox"/> Concretions
<input type="checkbox"/> Histic Epipedon	<input type="checkbox"/> High Organic Content in Surface Layer in Sandy Soils
<input type="checkbox"/> Sulfidic Odor	<input type="checkbox"/> Organic Streaking in Sandy Soils
<input type="checkbox"/> Aquic Moisture Regime	<input type="checkbox"/> Listed on Local Hydric Soils List
<input type="checkbox"/> Reducing Conditions	<input type="checkbox"/> Listed on National Hydric Soils List
<input type="checkbox"/> Gleyed or Low-Chroma Colors	<input type="checkbox"/> Other (Explain in Remarks)

Remarks:

WETLAND DETERMINATION

Hydrophytic Vegetation Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No (Check)	(Check)
Wetland Hydrology Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Is this Sampling Point Within a Wetland? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Hydric Soils Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Remarks	

DATA FORM
ROUTINE WETLAND DETERMINATION
(1987 COE Wetlands Delineation Manual)

Project/Site: <u>Tranvia de Carolina</u>	Date: <u>Jan 2007</u>
Applicant/Owner: <u>AFI, Municipio Carolina</u>	County: <u>Carolina</u>
Investigator: <u>RiveraLugo, PJ</u>	State: <u>Puerto Rico</u>
Do Normal Circumstances exist on the site? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Community ID: _____
Is the site significantly disturbed (Atypical Situation)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Transect ID: <u>39</u>
Is the area a potential Problem Area? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Plot ID: <u>a</u>
(If needed, explain on reverse.)	

VEGETATION

Dominant Plant Species	Stratum	Indicator	Dominant Plant Species	Stratum	Indicator
1. <u>Tabebuia rosea</u>	<u>T</u>	<u>NI</u>	9. _____	_____	_____
2. <u>Tabebuia heterophylla</u>	<u>T</u>	<u>FAC</u>	10. _____	_____	_____
3. <u>Albizia procera</u>	<u>T</u>	<u>NI</u>	11. _____	_____	_____
4. <u>Roystonea borinquena</u>	<u>T</u>	<u>FAC</u>	12. _____	_____	_____
5. <u>Sphagneticola trilobataH</u>	<u>NI</u>	_____	13. _____	_____	_____
6. _____	_____	_____	14. _____	_____	_____
7. _____	_____	_____	15. _____	_____	_____
8. _____	_____	_____	16. _____	_____	_____

Percent of Dominant Species that are OBL, FACW or FAC (excluding FAC-): _____

Remarks: _____

HYDROLOGY

<input type="checkbox"/> Recorded Data (Describe in Remarks): <input type="checkbox"/> Stream, Lake, or Tide Gauge <input type="checkbox"/> Aerial Photographs <input type="checkbox"/> Other <input type="checkbox"/> No Recorded Data Available	Wetland Hydrology Indicators: Primary Indicators: <input type="checkbox"/> Inundated <input type="checkbox"/> Saturated in Upper 12 Inches <input type="checkbox"/> Water Marks <input type="checkbox"/> Drift Lines <input type="checkbox"/> Sediment Deposits <input type="checkbox"/> Drainage Patterns in Wetlands Secondary Indicators (2 or more required): <input type="checkbox"/> Oxidized Root Channels in Upper 12 Inches <input type="checkbox"/> Water-Stained Leaves <input type="checkbox"/> Local Soil Survey Data <input type="checkbox"/> FAC-Neutral Test <input type="checkbox"/> Other (Explain in Remarks)
Field Observations: Depth of Surface Water: _____ (in.) Depth to Free Water in Pit: _____ (in.) Depth to Saturated Soil: _____ (in.)	
Remarks: _____	

SOILS

Map Unit Name (Series and Phase):		Soils from mixed origin		Drainage Class:	_____
Taxonomy (Subgroup):		_____		Field Observations	_____
				Confirm Mapped Type?	<input type="checkbox"/> Yes <input type="checkbox"/> No

Profile Descriptions:	Depth (inches)	Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc,

Hydric Soil Indicators:

<input type="checkbox"/> Histosol	<input type="checkbox"/> Concretions
<input type="checkbox"/> Histic Epipedon	<input type="checkbox"/> High Organic Content in Surface Layer in Sandy Soils
<input type="checkbox"/> Sulfidic Odor	<input type="checkbox"/> Organic Streaking in Sandy Soils
<input type="checkbox"/> Aquic Moisture Regime	<input type="checkbox"/> Listed on Local Hydric Soils List
<input type="checkbox"/> Reducing Conditions	<input type="checkbox"/> Listed on National Hydric Soils List
<input type="checkbox"/> Gleyed or Low-Chroma Colors	<input type="checkbox"/> Other (Explain in Remarks)

Remarks:

WETLAND DETERMINATION

Hydrophytic Vegetation Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No (Check)	(Check)
Wetland Hydrology Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Hydric Soils Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Is this Sampling Point Within a Wetland? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Remarks	

DATA FORM
ROUTINE WETLAND DETERMINATION
(1987 COE Wetlands Delineation Manual)

Project/Site: <u>Tranvia de Carolina</u>	Date: <u>Jan 2007</u>
Applicant/Owner: <u>AFI, Municipio Carolina</u>	County: <u>Carolina</u>
Investigator: <u>RiveraLugo,PJ</u>	State: <u>Puerto Rico</u>
Do Normal Circumstances exist on the site? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Community ID: _____
Is the site significantly disturbed (Atypical Situation)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Transect ID: <u>38</u>
Is the area a potential Problem Area? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Plot ID: <u>c</u>
(If needed, explain on reverse.)	

VEGETATION

Dominant Plant Species	Stratum	Indicator	Dominant Plant Species	Stratum	Indicator
1. <u>Bucidas buceras</u>	<u>T</u>	<u>FAC</u>	9. _____	_____	_____
2. <u>Urochloa mutica</u>	<u>H</u>	<u>FACW</u>	10. _____	_____	_____
3. <u>Tabebuia heterophylla</u>	<u>T</u>	<u>FAC</u>	11. _____	_____	_____
4. <u>Spathodea campanulata</u>	<u>T</u>	<u>FACU</u>	12. _____	_____	_____
5. <u>Albizia procera</u>	<u>T</u>	<u>NI</u>	13. _____	_____	_____
6. <u>Vigna luteola</u>	<u>H</u>	<u>FAC</u>	14. _____	_____	_____
7. <u>Ixora coccinea</u>	<u>S</u>	<u>NI</u>	15. _____	_____	_____
8. _____	_____	_____	16. _____	_____	_____

Percent of Dominant Species that are OBL, FACW or FAC (excluding FAC-): _____

Remarks: _____

HYDROLOGY

<input type="checkbox"/> Recorded Data (Describe in Remarks): <input type="checkbox"/> Stream, Lake, or Tide Gauge <input type="checkbox"/> Aerial Photographs <input type="checkbox"/> Other <input type="checkbox"/> No Recorded Data Available	Wetland Hydrology Indicators: Primary Indicators: <input type="checkbox"/> Inundated <input type="checkbox"/> Saturated in Upper 12 Inches <input type="checkbox"/> Water Marks <input type="checkbox"/> Drift Lines <input type="checkbox"/> Sediment Deposits <input type="checkbox"/> Drainage Patterns in Wetlands Secondary Indicators (2 or more required): <input type="checkbox"/> Oxidized Root Channels in Upper 12 Inches <input type="checkbox"/> Water-Stained Leaves <input type="checkbox"/> Local Soil Survey Data <input type="checkbox"/> FAC-Neutral Test <input type="checkbox"/> Other (Explain in Remarks)
Field Observations: Depth of Surface Water: _____ (in.) Depth to Free Water in Pit: _____ (in.) Depth to Saturated Soil: _____ (in.)	
Remarks: _____	

SOILS

Map Unit Name (Series and Phase):		Soils from mixed origin		Drainage Class:	_____
Taxonomy (Subgroup):		_____		Field Observations	_____
				Confirm Mapped Type?	<input type="checkbox"/> Yes <input type="checkbox"/> No

Profile Descriptions: Depth (inches)	Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc,
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____

Hydric Soil Indicators:

<input type="checkbox"/> Histosol	<input type="checkbox"/> Concretions
<input type="checkbox"/> Histic Epipedon	<input type="checkbox"/> High Organic Content in Surface Layer in Sandy Soils
<input type="checkbox"/> Sulfidic Odor	<input type="checkbox"/> Organic Streaking in Sandy Soils
<input type="checkbox"/> Aquic Moisture Regime	<input type="checkbox"/> Listed on Local Hydric Soils List
<input type="checkbox"/> Reducing Conditions	<input type="checkbox"/> Listed on National Hydric Soils List
<input type="checkbox"/> Gleyed or Low-Chroma Colors	<input type="checkbox"/> Other (Explain in Remarks)

Remarks:

WETLAND DETERMINATION

Hydrophytic Vegetation Present?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	(Check)		
Wetland Hydrology Present?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No			
Hydric Soils Present?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No			
				Is this Sampling Point Within a Wetland?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No

Remarks

DATA FORM
ROUTINE WETLAND DETERMINATION
(1987 COE Wetlands Delineation Manual)

Project/Site: <u>Tranvia de Carolina</u>	Date: <u>Jan 2007</u>
Applicant/Owner: <u>AFI, Municipio Carolina</u>	County: <u>Carolina</u>
Investigator: <u>RiveraLugo,PJ</u>	State: <u>Puerto Rico</u>
Do Normal Circumstances exist on the site? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Community ID: _____
Is the site significantly disturbed (Atypical Situation)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Transect ID: <u>38</u>
Is the area a potential Problem Area? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Plot ID: <u>b</u>
(If needed, explain on reverse.)	

VEGETATION

Dominant Plant Species	Stratum	Indicator	Dominant Plant Species	Stratum	Indicator
1. <u>Bucidas buceras</u>	<u>T</u>	<u>FAC</u>	9. _____	_____	_____
2. <u>Urochloa mutica</u>	<u>H</u>	<u>FACW</u>	10. _____	_____	_____
3. <u>Tabebuia heterophylla</u>	<u>T</u>	<u>FAC</u>	11. _____	_____	_____
4. <u>Spathodea campanulata</u>	<u>T</u>	<u>FACU</u>	12. _____	_____	_____
5. <u>Albizia procera</u>	<u>T</u>	<u>NI</u>	13. _____	_____	_____
6. <u>Vigna luteola</u>	<u>H</u>	<u>FAC</u>	14. _____	_____	_____
7. <u>Ixora coccinea</u>	<u>S</u>	<u>NI</u>	15. _____	_____	_____
8. _____	_____	_____	16. _____	_____	_____

Percent of Dominant Species that are OBL, FACW or FAC (excluding FAC-): _____

Remarks: _____

HYDROLOGY

<input type="checkbox"/> Recorded Data (Describe in Remarks): <input type="checkbox"/> Stream, Lake, or Tide Gauge <input type="checkbox"/> Aerial Photographs <input type="checkbox"/> Other <input type="checkbox"/> No Recorded Data Available	Wetland Hydrology Indicators: Primary Indicators: <input type="checkbox"/> Inundated <input type="checkbox"/> Saturated in Upper 12 Inches <input type="checkbox"/> Water Marks <input type="checkbox"/> Drift Lines <input type="checkbox"/> Sediment Deposits <input type="checkbox"/> Drainage Patterns in Wetlands Secondary Indicators (2 or more required): <input type="checkbox"/> Oxidized Root Channels in Upper 12 Inches <input type="checkbox"/> Water-Stained Leaves <input type="checkbox"/> Local Soil Survey Data <input type="checkbox"/> FAC-Neutral Test <input type="checkbox"/> Other (Explain in Remarks)
Field Observations: Depth of Surface Water: _____ (in.) Depth to Free Water in Pit: _____ (in.) Depth to Saturated Soil: _____ (in.)	
Remarks: _____	

SOILS

Map Unit Name (Series and Phase):		Soils from mixed origin		Drainage Class:	_____
Taxonomy (Subgroup):		_____		Field Observations	_____
				Confirm Mapped Type?	<input type="checkbox"/> Yes <input type="checkbox"/> No

Profile Descriptions:	Matrix Color	Mottle Colors	Mottle Abundance/	Texture, Concretions,
Depth (inches) Horizon	(Munsell Moist)	(Munsell Moist)	Size/Contrast	Structure, etc,
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Hydric Soil Indicators:

<input type="checkbox"/> Histosol	<input type="checkbox"/> Concretions
<input type="checkbox"/> Histic Epipedon	<input type="checkbox"/> High Organic Content in Surface Layer in Sandy Soils
<input type="checkbox"/> Sulfidic Odor	<input type="checkbox"/> Organic Streaking in Sandy Soils
<input type="checkbox"/> Aquic Moisture Regime	<input type="checkbox"/> Listed on Local Hydric Soils List
<input type="checkbox"/> Reducing Conditions	<input type="checkbox"/> Listed on National Hydric Soils List
<input type="checkbox"/> Gleyed or Low-Chroma Colors	<input type="checkbox"/> Other (Explain in Remarks)

Remarks:

WETLAND DETERMINATION

Hydrophytic Vegetation Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No (Check)	(Check)
Wetland Hydrology Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Hydric Soils Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Is this Sampling Point Within a Wetland? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No

Remarks

DATA FORM
ROUTINE WETLAND DETERMINATION
(1987 COE Wetlands Delineation Manual)

Project/Site: <u>Tranvia de Carolina</u>	Date: <u>Jan 2007</u>
Applicant/Owner: <u>AFI, Municipio Carolina</u>	County: <u>Carolina</u>
Investigator: <u>RiveraLugo, PJ</u>	State: <u>Puerto Rico</u>
Do Normal Circumstances exist on the site? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Community ID: _____
Is the site significantly disturbed (Atypical Situation)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Transect ID: <u>38</u>
Is the area a potential Problem Area? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Plot ID: <u>a</u>
(If needed, explain on reverse.)	

VEGETATION

Dominant Plant Species	Stratum	Indicator	Dominant Plant Species	Stratum	Indicator
1. <u>Bucidas buceras</u>	<u>T</u>	<u>FAC</u>	9. _____	_____	_____
2. <u>Urochloa mutica</u>	<u>H</u>	<u>FACW</u>	10. _____	_____	_____
3. <u>Tabebuia heterophylla</u>	<u>T</u>	<u>FAC</u>	11. _____	_____	_____
4. <u>Spathodea campanulata</u>	<u>T</u>	<u>FACU</u>	12. _____	_____	_____
5. <u>Albizia procera</u>	<u>T</u>	<u>NI</u>	13. _____	_____	_____
6. <u>Vigna luteola</u>	<u>H</u>	<u>FAC</u>	14. _____	_____	_____
7. <u>Ixora coccinea</u>	<u>S</u>	<u>NI</u>	15. _____	_____	_____
8. _____	_____	_____	16. _____	_____	_____

Percent of Dominant Species that are OBL, FACW or FAC (excluding FAC-): _____

Remarks: _____

HYDROLOGY

<input type="checkbox"/> Recorded Data (Describe in Remarks): <input type="checkbox"/> Stream, Lake, or Tide Gauge <input type="checkbox"/> Aerial Photographs <input type="checkbox"/> Other <input type="checkbox"/> No Recorded Data Available	Wetland Hydrology Indicators: Primary Indicators: <input type="checkbox"/> Inundated <input type="checkbox"/> Saturated in Upper 12 Inches <input type="checkbox"/> Water Marks <input type="checkbox"/> Drift Lines <input type="checkbox"/> Sediment Deposits <input type="checkbox"/> Drainage Patterns in Wetlands Secondary Indicators (2 or more required): <input type="checkbox"/> Oxidized Root Channels in Upper 12 Inches <input type="checkbox"/> Water-Stained Leaves <input type="checkbox"/> Local Soil Survey Data <input type="checkbox"/> FAC-Neutral Test <input type="checkbox"/> Other (Explain in Remarks)
Field Observations: Depth of Surface Water: _____ (in.) Depth to Free Water in Pit: _____ (in.) Depth to Saturated Soil: _____ (in.)	
Remarks: _____	

SOILS

Map Unit Name (Series and Phase):		Soils from mixed origin, paved		Drainage Class:	_____
Taxonomy (Subgroup):		_____		Field Observations	_____
				Confirm Mapped Type?	<input type="checkbox"/> Yes <input type="checkbox"/> No

Profile Descriptions: Depth (inches)	Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc,

Hydric Soil Indicators:

<input type="checkbox"/> Histosol	<input type="checkbox"/> Concretions
<input type="checkbox"/> Histic Epipedon	<input type="checkbox"/> High Organic Content in Surface Layer in Sandy Soils
<input type="checkbox"/> Sulfidic Odor	<input type="checkbox"/> Organic Streaking in Sandy Soils
<input type="checkbox"/> Aquic Moisture Regime	<input type="checkbox"/> Listed on Local Hydric Soils List
<input type="checkbox"/> Reducing Conditions	<input type="checkbox"/> Listed on National Hydric Soils List
<input type="checkbox"/> Gleyed or Low-Chroma Colors	<input type="checkbox"/> Other (Explain in Remarks)

Remarks:

WETLAND DETERMINATION

<p>Hydrophytic Vegetation Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No (Check)</p> <p>Wetland Hydrology Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p> <p>Hydric Soils Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p>	<p style="text-align: right;">(Check)</p> <p>Is this Sampling Point Within a Wetland? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p>
<p>Remarks</p>	

DATA FORM
ROUTINE WETLAND DETERMINATION
(1987 COE Wetlands Delineation Manual)

Project/Site: <u>Tranvia de Carolina</u>	Date: <u>Jan 2007</u>
Applicant/Owner: <u>AFI, Municipio Carolina</u>	County: <u>Carolina</u>
Investigator: <u>RiveraLugo,PJ</u>	State: <u>Puerto Rico</u>
Do Normal Circumstances exist on the site? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Community ID: _____
Is the site significantly disturbed (Atypical Situation)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Transect ID: <u>37</u>
Is the area a potential Problem Area? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Plot ID: <u>c</u>
(If needed, explain on reverse.)	

VEGETATION

Dominant Plant Species	Stratum	Indicator	Dominant Plant Species	Stratum	Indicator
1. <u>Bucidas buceras</u>	<u>T</u>	<u>FAC</u>	9. _____	_____	_____
2. <u>Pterocarpus indicus</u>	<u>T</u>	<u>NI</u>	10. _____	_____	_____
3. <u>Swietenia mahagony</u>	<u>T</u>	<u>NI</u>	11. _____	_____	_____
4. <u>Leucaena leucocephala</u>	<u>T</u>	<u>FAC</u>	12. _____	_____	_____
5. <u>Bidens alba</u>	<u>H</u>	<u>NI</u>	13. _____	_____	_____
6. _____	_____	_____	14. _____	_____	_____
7. _____	_____	_____	15. _____	_____	_____
8. _____	_____	_____	16. _____	_____	_____

Percent of Dominant Species that are OBL, FACW or FAC (excluding FAC-): _____

Remarks: _____

HYDROLOGY

<input type="checkbox"/> Recorded Data (Describe in Remarks): <input type="checkbox"/> Stream, Lake, or Tide Gauge <input type="checkbox"/> Aerial Photographs <input type="checkbox"/> Other <input type="checkbox"/> No Recorded Data Available	Wetland Hydrology Indicators: Primary Indicators: <input type="checkbox"/> Inundated <input type="checkbox"/> Saturated in Upper 12 Inches <input type="checkbox"/> Water Marks <input type="checkbox"/> Drift Lines <input type="checkbox"/> Sediment Deposits <input type="checkbox"/> Drainage Patterns in Wetlands Secondary Indicators (2 or more required): <input type="checkbox"/> Oxidized Root Channels in Upper 12 Inches <input type="checkbox"/> Water-Stained Leaves <input type="checkbox"/> Local Soil Survey Data <input type="checkbox"/> FAC-Neutral Test <input type="checkbox"/> Other (Explain in Remarks)
Field Observations: Depth of Surface Water: _____ (in.) Depth to Free Water in Pit: _____ (in.) Depth to Saturated Soil: _____ (in.)	
Remarks: _____	

SOILS

Map Unit Name (Series and Phase):		Soils from mixed origin, paved		Drainage Class:	_____
Taxonomy (Subgroup):		_____		Field Observations	_____
				Confirm Mapped Type?	<input type="checkbox"/> Yes <input type="checkbox"/> No

Profile Descriptions:	Depth (inches)	Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc,

Hydric Soil Indicators:

<input type="checkbox"/> Histosol	<input type="checkbox"/> Concretions
<input type="checkbox"/> Histic Epipedon	<input type="checkbox"/> High Organic Content in Surface Layer in Sandy Soils
<input type="checkbox"/> Sulfidic Odor	<input type="checkbox"/> Organic Streaking in Sandy Soils
<input type="checkbox"/> Aquic Moisture Regime	<input type="checkbox"/> Listed on Local Hydric Soils List
<input type="checkbox"/> Reducing Conditions	<input type="checkbox"/> Listed on National Hydric Soils List
<input type="checkbox"/> Gleyed or Low-Chroma Colors	<input type="checkbox"/> Other (Explain in Remarks)

Remarks:

WETLAND DETERMINATION

Hydrophytic Vegetation Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No (Check) Wetland Hydrology Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Hydric Soils Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	(Check) Is this Sampling Point Within a Wetland? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Remarks	

DATA FORM
ROUTINE WETLAND DETERMINATION
(1987 COE Wetlands Delineation Manual)

Project/Site: <u>Tranvia de Carolina</u>	Date: <u>Jan 2007</u>
Applicant/Owner: <u>AFI, Municipio Carolina</u>	County: <u>Carolina</u>
Investigator: <u>RiveraLugo, PJ</u>	State: <u>Puerto Rico</u>
Do Normal Circumstances exist on the site? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Community ID: _____
Is the site significantly disturbed (Atypical Situation)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Transect ID: <u>37</u>
Is the area a potential Problem Area? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No (If needed, explain on reverse.)	Plot ID: <u>b</u>

VEGETATION

Dominant Plant Species	Stratum	Indicator	Dominant Plant Species	Stratum	Indicator
1. <u>Bucidas buceras</u>	<u>T</u>	<u>FAC</u>	9. _____	_____	_____
2. <u>Pterocarpus indicus</u>	<u>T</u>	<u>NI</u>	10. _____	_____	_____
3. <u>Swietenia mahagony</u>	<u>T</u>	<u>NI</u>	11. _____	_____	_____
4. <u>Leucaena leucocephala</u>	<u>T</u>	<u>FAC</u>	12. _____	_____	_____
5. <u>Bidens alba</u>	<u>H</u>	<u>NI</u>	13. _____	_____	_____
6. _____	_____	_____	14. _____	_____	_____
7. _____	_____	_____	15. _____	_____	_____
8. _____	_____	_____	16. _____	_____	_____

Percent of Dominant Species that are OBL, FACW or FAC (excluding FAC-): _____

Remarks: _____

HYDROLOGY

<input type="checkbox"/> Recorded Data (Describe in Remarks): <input type="checkbox"/> Stream, Lake, or Tide Gauge <input type="checkbox"/> Aerial Photographs <input type="checkbox"/> Other <input type="checkbox"/> No Recorded Data Available	Wetland Hydrology Indicators: Primary Indicators: <input type="checkbox"/> Inundated <input type="checkbox"/> Saturated in Upper 12 Inches <input type="checkbox"/> Water Marks <input type="checkbox"/> Drift Lines <input type="checkbox"/> Sediment Deposits <input type="checkbox"/> Drainage Patterns in Wetlands Secondary Indicators (2 or more required): <input type="checkbox"/> Oxidized Root Channels in Upper 12 Inches <input type="checkbox"/> Water-Stained Leaves <input type="checkbox"/> Local Soil Survey Data <input type="checkbox"/> FAC-Neutral Test <input type="checkbox"/> Other (Explain in Remarks)
Field Observations: Depth of Surface Water: _____ (in.) Depth to Free Water in Pit: _____ (in.) Depth to Saturated Soil: _____ (in.)	
Remarks: _____	

SOILS

Map Unit Name (Series and Phase):		Soils from mixed origin, paved	Drainage Class: _____		
Taxonomy (Subgroup):		_____	Field Observations _____		
			Confirm Mapped Type? <input type="checkbox"/> Yes <input type="checkbox"/> No		
Profile Descriptions:					
Depth (inches)	Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc,
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
Hydric Soil Indicators:					
<input type="checkbox"/> Histosol		<input type="checkbox"/> Concretions			
<input type="checkbox"/> Histic Epipedon		<input type="checkbox"/> High Organic Content in Surface Layer in Sandy Soils			
<input type="checkbox"/> Sulfidic Odor		<input type="checkbox"/> Organic Streaking in Sandy Soils			
<input type="checkbox"/> Aquic Moisture Regime		<input type="checkbox"/> Listed on Local Hydric Soils List			
<input type="checkbox"/> Reducing Conditions		<input type="checkbox"/> Listed on National Hydric Soils List			
<input type="checkbox"/> Gleyed or Low-Chroma Colors		<input type="checkbox"/> Other (Explain in Remarks)			
Remarks:					

WETLAND DETERMINATION

Hydrophytic Vegetation Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No (Check)	(Check)
Wetland Hydrology Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Hydric Soils Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Is this Sampling Point Within a Wetland? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Remarks	

DATA FORM
ROUTINE WETLAND DETERMINATION
(1987 COE Wetlands Delineation Manual)

Project/Site: <u>Tranvia de Carolina</u>	Date: <u>Jan 2007</u>
Applicant/Owner: <u>AFI, Municipio Carolina</u>	County: <u>Carolina</u>
Investigator: <u>RiveraLugo,PJ</u>	State: <u>Puerto Rico</u>
Do Normal Circumstances exist on the site? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Community ID: _____
Is the site significantly disturbed (Atypical Situation)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Transect ID: <u>37</u>
Is the area a potential Problem Area? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No (If needed, explain on reverse.)	Plot ID: <u>a</u>

VEGETATION

Dominant Plant Species	Stratum	Indicator	Dominant Plant Species	Stratum	Indicator
1. <u>Bucidas buceras</u>	<u>T</u>	<u>FAC</u>	9. _____	_____	_____
2. <u>Pterocarpus indicus</u>	<u>T</u>	<u>NI</u>	10. _____	_____	_____
3. <u>Swietenia mahagony</u>	<u>T</u>	<u>NI</u>	11. _____	_____	_____
4. <u>Leucaena leucocephala</u>	<u>T</u>	<u>FAC</u>	12. _____	_____	_____
5. <u>Bidens alba</u>	<u>H</u>	<u>NI</u>	13. _____	_____	_____
6. _____	_____	_____	14. _____	_____	_____
7. _____	_____	_____	15. _____	_____	_____
8. _____	_____	_____	16. _____	_____	_____

Percent of Dominant Species that are OBL, FACW or FAC (excluding FAC-). _____

Remarks: _____

HYDROLOGY

<input type="checkbox"/> Recorded Data (Describe in Remarks): <input type="checkbox"/> Stream, Lake, or Tide Gauge <input type="checkbox"/> Aerial Photographs <input type="checkbox"/> Other <input type="checkbox"/> No Recorded Data Available	Wetland Hydrology Indicators: Primary Indicators: <input type="checkbox"/> Inundated <input type="checkbox"/> Saturated in Upper 12 Inches <input type="checkbox"/> Water Marks <input type="checkbox"/> Drift Lines <input type="checkbox"/> Sediment Deposits <input type="checkbox"/> Drainage Patterns in Wetlands Secondary Indicators (2 or more required): <input type="checkbox"/> Oxidized Root Channels in Upper 12 Inches <input type="checkbox"/> Water-Stained Leaves <input type="checkbox"/> Local Soil Survey Data <input type="checkbox"/> FAC-Neutral Test <input type="checkbox"/> Other (Explain in Remarks)
Field Observations: Depth of Surface Water: _____ (in.) Depth to Free Water in Pit: _____ (in.) Depth to Saturated Soil: _____ (in.)	
Remarks: _____	

SOILS

Map Unit Name (Series and Phase):		Soil from mixed origin, paved		Drainage Class:	_____
Taxonomy (Subgroup):		_____		Field Observations	_____
				Confirm Mapped Type?	<input type="checkbox"/> Yes <input type="checkbox"/> No

Profile Descriptions: Depth (inches)	Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc,

Hydric Soil Indicators:

<input type="checkbox"/> Histosol	<input type="checkbox"/> Concretions
<input type="checkbox"/> Histic Epipedon	<input type="checkbox"/> High Organic Content in Surface Layer in Sandy Soils
<input type="checkbox"/> Sulfidic Odor	<input type="checkbox"/> Organic Streaking in Sandy Soils
<input type="checkbox"/> Aquic Moisture Regime	<input type="checkbox"/> Listed on Local Hydric Soils List
<input type="checkbox"/> Reducing Conditions	<input type="checkbox"/> Listed on National Hydric Soils List
<input type="checkbox"/> Gleyed or Low-Chroma Colors	<input type="checkbox"/> Other (Explain in Remarks)

Remarks:

WETLAND DETERMINATION

<p>Hydrophytic Vegetation Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No (Check)</p> <p>Wetland Hydrology Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p> <p>Hydric Soils Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p>	<p style="text-align: right;">(Check)</p> <p>Is this Sampling Point Within a Wetland? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p>
<p>Remarks</p>	

DATA FORM
ROUTINE WETLAND DETERMINATION
(1987 COE Wetlands Delineation Manual)

Project/Site: <u>Tranvia de Carolina</u>	Date: <u>Jan 2007</u>
Applicant/Owner: <u>AFI, Municipio Carolina</u>	County: <u>Carolina</u>
Investigator: <u>RiveraLugo,PJ</u>	State: <u>Puerto Rico</u>
Do Normal Circumstances exist on the site? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Community ID: _____
Is the site significantly disturbed (Atypical Situation)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Transect ID: <u>36</u>
Is the area a potential Problem Area? (If needed, explain on reverse.) <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Plot ID: <u>c</u>

VEGETATION

Dominant Plant Species	Stratum	Indicator	Dominant Plant Species	Stratum	Indicator
1. <u>Eleusine indica</u>	<u>H</u>	<u>FAC</u>	9. _____	_____	_____
2. <u>Bucidas buceras</u>	<u>T</u>	<u>FAC</u>	10. _____	_____	_____
3. <u>Ficus microcarpa</u>	<u>T</u>	<u>NI</u>	11. _____	_____	_____
4. <u>Ceiba pentandra</u>	<u>T</u>	<u>NI</u>	12. _____	_____	_____
5. <u>Ixora coccinea</u>	<u>S</u>	<u>NI</u>	13. _____	_____	_____
6. <u>Axonopus compressus</u>	<u>H</u>	<u>FAC</u>	14. _____	_____	_____
7. _____	_____	_____	15. _____	_____	_____
8. _____	_____	_____	16. _____	_____	_____

Percent of Dominant Species that are OBL, FACW or FAC
(excluding FAC-).

Remarks:

HYDROLOGY

<input type="checkbox"/> Recorded Data (Describe in Remarks): <input type="checkbox"/> Stream, Lake, or Tide Gauge <input type="checkbox"/> Aerial Photographs <input type="checkbox"/> Other <input type="checkbox"/> No Recorded Data Available	Wetland Hydrology Indicators: Primary Indicators: <input type="checkbox"/> Inundated <input type="checkbox"/> Saturated in Upper 12 Inches <input type="checkbox"/> Water Marks <input type="checkbox"/> Drift Lines <input type="checkbox"/> Sediment Deposits <input type="checkbox"/> Drainage Patterns in Wetlands Secondary Indicators (2 or more required): <input type="checkbox"/> Oxidized Root Channels in Upper 12 Inches <input type="checkbox"/> Water-Stained Leaves <input type="checkbox"/> Local Soil Survey Data <input type="checkbox"/> FAC-Neutral Test <input type="checkbox"/> Other (Explain in Remarks)
Field Observations: Depth of Surface Water: _____ (in.) Depth to Free Water in Pit: _____ (in.) Depth to Saturated Soil: _____ (in.)	
Remarks:	

SOILS

Map Unit Name (Series and Phase):		Soil from mixed origin, paved		Drainage Class:	_____
Taxonomy (Subgroup):		_____		Field Observations	_____
				Confirm Mapped Type?	<input type="checkbox"/> Yes <input type="checkbox"/> No

Profile Descriptions: Depth (inches)	Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc,

Hydric Soil Indicators:

<input type="checkbox"/> Histosol	<input type="checkbox"/> Concretions
<input type="checkbox"/> Histic Epipedon	<input type="checkbox"/> High Organic Content in Surface Layer in Sandy Soils
<input type="checkbox"/> Sulfidic Odor	<input type="checkbox"/> Organic Streaking in Sandy Soils
<input type="checkbox"/> Aquic Moisture Regime	<input type="checkbox"/> Listed on Local Hydric Soils List
<input type="checkbox"/> Reducing Conditions	<input type="checkbox"/> Listed on National Hydric Soils List
<input type="checkbox"/> Gleyed or Low-Chroma Colors	<input type="checkbox"/> Other (Explain in Remarks)

Remarks:

WETLAND DETERMINATION

Hydrophytic Vegetation Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No (Check) Wetland Hydrology Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Hydric Soils Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	_____ (Check) Is this Sampling Point Within a Wetland? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Remarks	

DATA FORM
ROUTINE WETLAND DETERMINATION
(1987 COE Wetlands Delineation Manual)

Project/Site: <u>Tranvia de Carolina</u>	Date: <u>Jan 2007</u>
Applicant/Owner: <u>AFI, Municipio Carolina</u>	County: <u>Carolina</u>
Investigator: <u>RiveraLugo, PJ</u>	State: <u>Puerto Rico</u>
Do Normal Circumstances exist on the site? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Community ID: _____
Is the site significantly disturbed (Atypical Situation)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Transect ID: <u>36</u>
Is the area a potential Problem Area? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Plot ID: <u>b</u>
(If needed, explain on reverse.)	

VEGETATION

Dominant Plant Species	Stratum	Indicator	Dominant Plant Species	Stratum	Indicator
1. <u>Eleusine indica</u>	<u>H</u>	<u>FAC</u>	9. _____	_____	_____
2. <u>Bucidas buceras</u>	<u>T</u>	<u>FAC</u>	10. _____	_____	_____
3. <u>Ficus microcarpa</u>	<u>T</u>	<u>NI</u>	11. _____	_____	_____
4. <u>Ceiba pentandra</u>	<u>T</u>	<u>NI</u>	12. _____	_____	_____
5. <u>Ixora coccinea</u>	<u>S</u>	<u>NI</u>	13. _____	_____	_____
6. <u>Axonopus compressus</u>	<u>H</u>	<u>FAC</u>	14. _____	_____	_____
7. _____	_____	_____	15. _____	_____	_____
8. _____	_____	_____	16. _____	_____	_____

Percent of Dominant Species that are OBL, FACW or FAC (excluding FAC-): _____

Remarks: _____

HYDROLOGY

<input type="checkbox"/> Recorded Data (Describe in Remarks): <input type="checkbox"/> Stream, Lake, or Tide Gauge <input type="checkbox"/> Aerial Photographs <input type="checkbox"/> Other <input type="checkbox"/> No Recorded Data Available	Wetland Hydrology Indicators: Primary Indicators: <input type="checkbox"/> Inundated <input type="checkbox"/> Saturated in Upper 12 Inches <input type="checkbox"/> Water Marks <input type="checkbox"/> Drift Lines <input type="checkbox"/> Sediment Deposits <input type="checkbox"/> Drainage Patterns in Wetlands Secondary Indicators (2 or more required): <input type="checkbox"/> Oxidized Root Channels in Upper 12 Inches <input type="checkbox"/> Water-Stained Leaves <input type="checkbox"/> Local Soil Survey Data <input type="checkbox"/> FAC-Neutral Test <input type="checkbox"/> Other (Explain in Remarks)
Field Observations: Depth of Surface Water: _____ (in.) Depth to Free Water in Pit: _____ (in.) Depth to Saturated Soil: _____ (in.)	
Remarks: _____	

SOILS

Map Unit Name (Series and Phase):		Soil from mixed origin, paved		Drainage Class:	_____
Taxonomy (Subgroup):		_____		Field Observations	_____
				Confirm Mapped Type?	<input type="checkbox"/> Yes <input type="checkbox"/> No

Profile Descriptions:	Depth (inches)	Horizon	Matrix Color (Munsell Moist)	Mottle Colors (Munsell Moist)	Mottle Abundance/ Size/Contrast	Texture, Concretions, Structure, etc,

Hydric Soil Indicators:

<input type="checkbox"/> Histosol	<input type="checkbox"/> Concretions
<input type="checkbox"/> Histic Epipedon	<input type="checkbox"/> High Organic Content in Surface Layer in Sandy Soils
<input type="checkbox"/> Sulfidic Odor	<input type="checkbox"/> Organic Streaking in Sandy Soils
<input type="checkbox"/> Aquic Moisture Regime	<input type="checkbox"/> Listed on Local Hydric Soils List
<input type="checkbox"/> Reducing Conditions	<input type="checkbox"/> Listed on National Hydric Soils List
<input type="checkbox"/> Gleyed or Low-Chroma Colors	<input type="checkbox"/> Other (Explain in Remarks)

Remarks:

WETLAND DETERMINATION

Hydrophytic Vegetation Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No (Check) Wetland Hydrology Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Hydric Soils Present? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	(Check) Is this Sampling Point Within a Wetland? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Remarks	

DATA FORM
ROUTINE WETLAND DETERMINATION
(1987 COE Wetlands Delineation Manual)

Project/Site: <u>Tranvia de Carolina</u>	Date: <u>Jan 2007</u>
Applicant/Owner: <u>AFI, Municipio Carolina</u>	County: <u>Carolina</u>
Investigator: <u>RiveraLugo, PJ</u>	State: <u>Puerto Rico</u>
Do Normal Circumstances exist on the site? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Community ID: _____
Is the site significantly disturbed (Atypical Situation)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Transect ID: <u>36</u>
Is the area a potential Problem Area? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No (If needed, explain on reverse.)	Plot ID: <u>a</u>

VEGETATION

Dominant Plant Species	Stratum	Indicator	Dominant Plant Species	Stratum	Indicator
1. <u>Eleusine indica</u>	<u>H</u>	<u>FAC</u>	9. _____	_____	_____
2. <u>Bucidas buceras</u>	<u>T</u>	<u>FAC</u>	10. _____	_____	_____
3. <u>Ficus microcarpa</u>	<u>T</u>	<u>NI</u>	11. _____	_____	_____
4. <u>Ceiba pentandra</u>	<u>T</u>	<u>NI</u>	12. _____	_____	_____
5. <u>Ixora coccinea</u>	<u>S</u>	<u>NI</u>	13. _____	_____	_____
6. <u>Axonopus compressus</u>	<u>H</u>	<u>FAC</u>	14. _____	_____	_____
7. _____	_____	_____	15. _____	_____	_____
8. _____	_____	_____	16. _____	_____	_____

Percent of Dominant Species that are OBL, FACW or FAC (excluding FAC-): _____

Remarks: _____

HYDROLOGY

<input type="checkbox"/> Recorded Data (Describe in Remarks): <input type="checkbox"/> Stream, Lake, or Tide Gauge <input type="checkbox"/> Aerial Photographs <input type="checkbox"/> Other <input type="checkbox"/> No Recorded Data Available	Wetland Hydrology Indicators: Primary Indicators: <input type="checkbox"/> Inundated <input type="checkbox"/> Saturated in Upper 12 Inches <input type="checkbox"/> Water Marks <input type="checkbox"/> Drift Lines <input type="checkbox"/> Sediment Deposits <input type="checkbox"/> Drainage Patterns in Wetlands Secondary Indicators (2 or more required): <input type="checkbox"/> Oxidized Root Channels in Upper 12 Inches <input type="checkbox"/> Water-Stained Leaves <input type="checkbox"/> Local Soil Survey Data <input type="checkbox"/> FAC-Neutral Test <input type="checkbox"/> Other (Explain in Remarks)
Field Observations: Depth of Surface Water: _____ (in.) Depth to Free Water in Pit: _____ (in.) Depth to Saturated Soil: _____ (in.)	
Remarks: _____	